

February 17, 1982

Jim Martin

Sal Fanelli

re: Model 788 Safety Redesign

Based on discussion at today's Steering Committee meeting, the Plant needs input from Research on the items listed below. Please provide John Linde (PE/c) with a written note indicating status of these items ASAP!

Action Needed: (See p. 6 of Feb. 11th Committee Meeting Minutes.)

- ① Model drawing revision - when do we anticipate completing?
- ② Opinion about effect of black oxide coloring on function of the plunger
- when do we expect to have opinion?
- ③ Extend revision to 580's
- what is our recommendation? Schedule?
- ④ Potential for unsafe condition if new parts (springs, plungers, etc.) are interchanged with old parts?
- Run interchangeability tests to cover all possible combinations and measure safe on/off forces. Can we complete by next week? If not, when?

Please let me know by Friday, Feb. 19th, how you plan to respond to these questions.

Tanner C.