

Remington

REMINGTON ARMS COMPANY, INC.

PETERS

MANUFACTURERS OF

SPORTING FIREARMS

TRAPS

POWDER METAL PARTS

ILION, NEW YORK

AMMUNITION, BRIDGEPORT, CONNECTICUT

LONGOKE, ARKANSAS

SPORTING FIREARMS, AMMUNITION

TRAPS

TARGETS

ILION, NEW YORK 13357

TELEPHONE 315/394-9951

PETERS CARTRIDGE DIVISION

BRIDGEPORT, CONNECTICUT

TARGETS, ADA, OKLAHOMA

ATHENS, GEORGIA

HINDLAY, OHIO

CABLE—HARTLEY, BRIDGEPORT

MAY 17 1982

Ilion, New York
May 13, 1982

TO: RECOMMENDED GUNSMITH INFORMATION BULLETIN

CC1143

MODEL 700 - CHANGE IN OPERATION

Market research, over the past several years, shows that customer interest in the bolt lock feature on the Model 700 rifle has declined. As a result, we have removed it.

Elimination of the bolt lock permits the bolt handle to be raised when the safety switch is either in the "S" or "F" position, simplifying loading and unloading. Appropriate changes in the instruction books have been made.

Since this change does not involve any product obsolescence, the order number will remain the same and there will be no formal trade announcement. Any gun returned to Ilion Arms Service for repair will be returned to the customer with the same style safety switch it had when received.

R. L. St. John

RLSTJ:tpg