

SALES
DEPARTMENT

Remington
Rem-O-Gram

Quick Facts About
REMINGTON
PRODUCTS

10 01
KENNETH D. GREEN
A.D. BLDG.

cc: House Force

Bridgeport, Connecticut
March 24, 1983

RECEIVED
MAR 28 1983

K. D. GREEN

TO THE FIELD FORCE:

You have already received a request to contact your jobber customers, instructing them to hold further delivery of any Model Seven rifles on hand and to supply you with a list of dealers who have received delivery of Model Seven rifles.

Our ultimate intention is to update all Model Seven rifles shipped to date by means of a return to the nearest Remington warranty gunsmith service location or to Arms Service in Ilion.

We have discovered that if a Model Seven rifle is disassembled after it leaves the factory, it is possible for the rifle to be reassembled incorrectly, producing off-center trigger alignment that might cause subsequent malfunction of the trigger and accidental firing of the rifle. The updating service on the rifle will eliminate the possibility of such incorrect reassembly.

To accomplish this, you are requested to obtain:

1. A list of all Model Seven rifles and matching serial numbers still in an individual jobber's inventory.
2. A list from the jobber of the names and addresses of dealers to whom Model Seven rifles have been shipped, including serial numbers.

Both jobbers and dealers will then be contacted by Product Service with instructions on how to have the rifles updated. Consumer purchasers of Model Seven rifles will also be contacted by Product Service with a request and instructions to have the rifles updated.

REMINGTON ARMS COMPANY, INC., BRIDGEPORT 2, CONN.


Printed in U.S.A.

Field Force
Page 2
March 24, 1983

In all contact with jobbers, dealers, and retail customers on this subject, it is important to emphasize that the potential malfunction is remote, can occur only on a Model Seven rifle that has been disassembled and subsequently reassembled outside the factory, and that the update applies only to Model Seven rifles and not to any other Remington models.

This update is being incorporated into all Model Seven rifles to be shipped in the future.

Sincerely,



E. J. Conroy
Director of Sales

EJC/dr

R2514458