

P.I. VFS GUN EXAMINATION REPORT NUMBER: 314 MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 32622
 OUTSIDE WORK: SIGHTS REMOVED DATE: 12-3-80
SWIVEL STUDS ADDED FRONT bearing Pad FROM: DEMARCO SPT. GORE
removed in stock. 200 N SIDE DRIVING
 FIRED AMMO TYPE: NOT KNOWN BENNINGTON VERM
 & CONDITION: _____ GUN #: B6217994
 PROOF: REP INSP.: 122 TEST: 82 CODE: PA 3-11-80
 HEADING: OK GA./CAL.: 270
 BREACH OPENING: OK CHECKED BY: M HARDY
 RECOIL SHOULDERS: OK APPROVED: 9/13/81
 CHAMBER: OK APPROVED: 10/13/81
 TEST: _____ APPROVED: 2/13/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
BRIGHT MARKS ON TOP REC
EXTRACTOR BROKEN RIGHT SIDE OF RIVET

 COMPLAINT: RIFLE HAS FIRING PROBLEM

 INCIDENT: SHOT HOLE IN TRUCK - FSR

 COMMENTS: Trigger pull 3 3/4#, Passed Trick test

Unable to verify customer complaint. Gun
appears to be normal.

