

Rev. 2-15-61

P.I. YES GUN EXAMINATION REPORT NUMBER: 37 MODEL: 700 BDL LHM.
GENERAL CONDITION: SLIGHTLY WORN R #: 28088
OUTSIDE WORK: SCOPE MOUNTED DATE: 11-22-82
FIRED AMMO TYPE: UNKNOWN FROM: CAMPBELL LAND CO.
945 Texas & Commerce & W.D.
SUITE 350
HOUSTON, TX 77024
& CONDITION: _____ GUN #: 6859417
PROOF: R.E.P. 2 INSP.: 123 TEST: 63 CODE: 5-76
HEADING: O.K. GA./CAL.: .270 WIN.
BREECH OPENING: O.K. CHECKED BY: SAW
RECOIL SHOULDERS: O.K. APPROVED: 9/28 12/28/82
CHAMBER: O.K. APPROVED: 12/28/82
TEST: _____ APPROVED: P.N. 12/28/82
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: RWB 12-28-82

COMPLAINT: "... Rifle FIRED When I was TRYING To UNLOAD It..."

INCIDENT: MOVED THE SAFETY TO THE OFF POSITION
TO OPEN THE BAR.

COMMENTS: Replace fire control as requested by
customer.