

Report # 85/062

TEST TITLE: NIBAR'S Firing Pin Extruder Malfunction Test

GUN SERIAL NO.	LINE NO.	TOTAL NO. DAY CYC	LIVE RD. LINE RD.	SERIAL OF TEST	END OF TEST	TIME MADE	TYPE	CDAD	LIVE RD.	CDAD	TYPE	CDAD	END OF TEST	TIME MADE	TYPE	CDAD
1 B6697275	7500	3,000	50	.024"	.035"	MIN 4.00"	C	0	1000	5	0		1000	5	0	
2 B6695575	7500	3,500	50	.025"	.035"	MIN 4.00"	C	0	1000	5	0		1000	5	0	
3 B66922677	7500	1,500	50	.026"	.036"	MIN 4.00"	C	0	1000	5	0		1000	5	0	
4 B6696475	75000	1,500	50	.023"	.025"	MIN 4.00"	C	0	1000	5	0		1000	5	0	
5 B6696435	7,500	3,000	50	.034"	.032"	MIN 4.00"	C	0	1000	5	0		1000	5	0	
6 B6697139	7,500	3,000	50	.022"	.023"	MIN 4.00"	C	0	1000	5	0		1000	5	0	
7																
8																
9																
10																
11																
12																
13																
14																
15																
16	NOTES:	THESE WERE NO FIRING PIN OR EXTRUDER MALFUNCTIONS FOUND DURING THIS TEST. NO MALFUNCTIONS WERE CAUGHT BY MAGNETIC FIELD.														
17																
18																
19																
20																
21																
22																
23																
24																
25																
26																
27																
28																
29																
30																
31																
32																
33																
34																
35																