

PS 1429 RECEIVED

3-19-84

J. S.

DEAR REMINGTON ARMS,

MAR 29 1984

J.A.

STEKEL

I HAVE USED AND ENJOYED YOUR PRODUCTS MANY YEARS. THIS WINTER I've
ENCOUNTERED A HAIR PULLING PROBLEM WITH MY MODEL 700 BDL 30-06 (BOUGHT IN 1978).
COYOTE CALLING IN THE UPPER PENINSULA OF MICHIGAN IS VERY OFFICULT DUE TO THE HEAVY
FOLIAGE. FUR IS SIGHTED ONLY ONCE IN 15-20 STANDS. IF AN ANIMAL COMES IN, YOU'D BETTER
HIT IT BECAUSE THAT MAY BE IT FOR THE SEASON. THE FIRST TIME OUT THIS YEAR I CALLED
A BIG COYOTE. THE FIRING PIN WOULD NOT HIT THE PRIMER HARD ENOUGH TO MAKE IT GO, AND
MY PARTNER HAD TO DROP HIM WITH A RUGER 12 GA. SHOTGUN. VERY EMBARRASSING!

THIS WEEKEND IT HAPPENED AGAIN WITH WORSE RESULTS. AFTER THE FIRST PROBLEM, I
REMOVED THE BOLT AND WASHED THE MAJOR AMOUNT OF OIL OFF THE STROKES WITH WHITE GAS.
IN A GOOD CLEANING, I SET THE GUN OUTSIDE OVERNIGHT AT A TEMP OF -35°F. IT SHOT
EASILY AT ALL TEMPERATURES. THIS WEEKEND IT WAS ONLY ZERO. I HAD A NICE COYOTE IN THE
LINE AT 75 YARDS AND NOTHING HAPPENED. I WORKED A NEW ROUND IN SLOWLY AND LINED UP
~~ON THE BOLT, IT FROZE AT 100 FEET~~ DUE FOR THE 60 MPH COYOTE. TWO MORE ROUNDS
WOULD NOT FIRE AND THE FOURTH ROUND FINALLY WENT OFF WITH NO RESULTS. I HAVE HAD
THE 700 AND TURNED UP A RUGER NO. 1 WHICH HAS NO BOLT!

THIS CONDITION OF MY BOLT ACTION IS VERY DANGEROUS. ANOTHER DANGEROUS POINT IS THAT IT
MAY BE LOADED OR UNLOADED WHILE THE SAFETY IS ON.

CAN YOU HELP ME WITH THESE PROBLEMS? MY '06 HAS KILLED A DOZEN WHITETAIL BUCKS
& AN ELK. I USED TO HIT SOUP CANS AT 200 YARDS. IT USED TO BE MY FAVORITE RIFLE.

PLEASE HELP ME RESTORE MY 700 TO ITS POSITION OF PRIMACY. THANK YOU.

FRUSTRATED,

RECEIVED

MAR 27 1984

CONSUMER SERVICE

DENNIS VISSERING

SR BOX 191

MICHIGAN MI. 49861