RESEARCH TEST & MEASUREMENT LAB WORK REQUEST

| | | 1 | A DE TESTING |
|---------------|---|--|---|
| Developmental | | AREA OF TESTING Safety Related Litigation | |
| | tion Acceptance | | Warenouse Audit |
| | -Pilot | New Design | Cost Reduction |
| | | Design Change | |
| Pilo | | Plant Assistance | Stake |
| Pro | duction Acceptance | Plant Assistance | A Other MANGE |
| | FIREARM STAT'S | REPORT REO'D. | 5 / |
| МО | DOEL: 700 | | DATE REQUESTED: 4/12/59 |
| | L or GAGE: A-1/ | FORMAL | DATE NEEDED BY: 4/20/88 |
| | RREL TYPS: | TEST NESULTS | REQUESTED BY: JS/283 |
| | 00FED: YES NO | ONLY X | WORK ORDER NO: 4810// |
| | | <u> </u> | |
| | | TEST TYPE | |
| Stre | ength Test Ammuniti | on Test Dry Cycle T | |
| Fur | nation Test Environme | | |
| Acc | Customer Customer | Complaint Endurance | Test <u>YISUAL</u> |
| EXPLAIN | IN DETAIL THE REASON FOR T | HIS TEST: | |
| | | | |
| : | on chele - 6 | Fire controls wit | - > INC shosphele |
| | 3 | | • |
| | Lo 14° | ting to 10,000 | cg cles |
| | • • | II cont | |
| | | eally inspect - | , |
| | . Car | ntinue to 20,000 | o level |
| | | nd repeat visual | in rection |
| | a | ne repeat visue | , ms , re |
| | | | |
| | | | |
| | | • | |
| -GUNS ŘE | QUIRED: | • | |
| | | | |
| | SIX SAMPLES RETU | IRNED TO J. SHEDEK | ER FURTHER |
| | | | |
| TE | esting, | | |
| | • | | 11.20 CH |
| NOTE: I | NO firearms or parts will be tested i | | DATE COMPLETED: 4.28-88 |
| NOTE: I | • | | DATE COMPLETED: 4.28-88 TEST COMPLETED BY: 8.W. Now E |
| NOTE: 1 | NO firearms or parts will be tested i | nd both are delivered to | DATE COMPLETED: 4.28-88 TEST COMPLETED BY: 8.W. HOWE REPORT DATE: |
| NOTE: | NO firearms or parts will be tested i | nd both are delivered to r. All Work Requests are | |
| NOTE: | NO firearms or parts will be tested in accompanied by a Work Request, at the Labs by the designer or engineer | nd both are delivered to r. All Work Requests are | |
| NOTE: | NO firearms or parts will be tested in accompanied by a Work Request, at the Labs by the designer or engineer | nd both are delivered to r. All Work Requests are | |
| NOTE: | NO firearms or parts will be tested in accompanied by a Work Request, at the Labs by the designer or engineer | nd both are delivered to r. All Work Requests are | |
| NOTE: | NO firearms or parts will be tested in accompanied by a Work Request, at the Labs by the designer or engineer | nd both are delivered to r. All Work Requests are | |