
THE CHAFFIN LAW FIRM A Professional Corporation

ROBERT A. CHAFFIN ANA ARANGO CHAFFIN PAUL R. MILLER" STEVEN D. NAUMANN""

*Licensed in Texas and New York Licensed in Texas and Louisiana ""Licensed in Texas and Nevada



being pulled. It is our understanding that you may have had a similar experience with a Remington Model 700 rifle. We are attempting to gather as much information as possible about other instances where a Model 700 rifle has discharged without the trigger being pulled.

We would appreciate it very much if you would complete the attached questionnaire and return it to our office in the self-addressed, stamped envelope which we have provided for your convenience. Please feel free to call me if you have any questions or if you need any additional information. Our toll-free numbers are 1-800-580-8570 in Texas and 1-800-866-8570 outside of Texas.

Thank you for your prompt attention and assistance in this matter. The Water to the same of the Sincerely,

THE CHAFFIN LAW FIRM

Robert A. Chaffin

RAC/mlt



1 Sont Tho Gun Back ton Remington in early Jan, 1979 They had me send The Fifthe To them, they seid thee replaced the Boil & firm, port and also send intersome knowny To have my Track windows repeated. I forget the papers amount towns in the middle of a north Duouse and I might all of the papers. But I did flux a unty Amulape from the