

FROM: THOMAS AMANN

RD 2 M450

MONROE New York 10950

TO: ARMS Service Division

Remington Arms Co, Inc.

ILION New York 13357

DATE 11-10-90

Gentlemen,

The problem with my Remington
35 wheel # C6287817 Classic Model is
AS follows: OPEN BOLT with safty on F, close
BOLT, WEAPON doesn't COCK. OPEN BOLT with
WEAPON SAfty on SAFE, CLOSE bolt weapon COCKS.
REMOVE SAfty to fire, WEAPON shoots. TRIGGER is
NOT being touched. Rifle shoots as safty is
moved.

Thank
Thomas Amann