## Remington.

22 April 2009

Detective Corey M. Helton Hobbs Police Department 301 N. Dalmont Hobbs, NM 88240

RE: Model 700 Serial #: C6747095

Dear Detective Helton,

We have completed our examination of the Model 700 rifle described above.

We could not duplicate the concern. We inspected the entire rifle; function tested the rifle, and ran additional tests to simulate "slapping the bolt handle up" at no time were we able to get the firing pin to follow down.

Because of a copy of a fax, included with the paper work with the rifle, from attorney Jeffrey Hightower, we have not made any changes to the rifle. We will be returning the rifle to your department in its "as received condition" with one minor exception. Some of the camouflage paint was removed to read the serial number.

We have offered as a gesture of good will to install a new trigger assembly and that offer will stand once any legal action has been settled.

Sincerely,

Fred Supry, Manager Product Service and Law Enforcement Training Remington Arms Company 14 Hoefler Avenue Ilion, NY 13357

Phone: 315-895-3606

E-mail: fred.supry@remington.com

Remington Arms Company, Inc. • 14 Hoefler Avenue • Ilion, NY 13357 Phone 315-895-3200 • www.remington.com