

ORDER
R 91-26294

IDE

25-06

BDL

ER, DUANE
X 96A
TYNC
68355

Remington
Recently spoke with rep of
your company about enclosed Rifle
It was advised to send to this address
for repair.

Recap of problem:

Past couple years gun has discharged
on 3 occasions w/o pulling trigger.

Twice as gun was being placed in
Fire position from safe and once when
bolt was raised slightly to unload.

Owner of gun was trying to show me
what happens w/ the unloaded weapon &
after placing gun on & off safety App 10
times firing pin did fall on the empty
chamber. We then tried for App 12 hr
to get it to do it again but was unsuccessful.
Owner did state that on several occasions when
gun was empty ~~this~~ this would happen either
when placing gun in fire position or when starting
to bolt gun.

ESTIMATED	VIA
	UPS
REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

INSPECT	
F1	fire position
F2	
F3	
F4	
F5	

it was made
success
in duty and
to 25 pounds
at present
can offer a
in currently at
me of good will.

Thank

Bruster's Place
RR #1 Box 96A
Falls City NE 68355
547-074-01-96-11833

D. Ambuster

Duane Ambuster
RR #1 BX 96A
Falls City NE 68355
PBX 402-245-5014

GALLERY TESTER

DATE

DATE

DATE

TARGET

PATTERN

DATE

DATE