
From: Joy, Robert L.
Sent: Thursday, March 13, 2008 10:40 AM
To: Becker, Craig
Cc: Perniciaro, Stephen; Orf, Robert J.; Shoemaker, Christopher D.; Doolittle, James F.; Farrington, Kenneth L.; Marley, Matthew M.
Subject: 700 XMP Updated Sear Verification
Attachments: 700 XMP Updated MIM Sear Verification 20080006 031208.pdf

Craig,

Here is the verification test report on the recently updated MIM sear design that was done to eliminate possible bolt bind issues. The components you submitted passed all of our test successfully. Let me know if you have questions.

Bob

*Robert L. Joy
Staff Engineer
Supervisor - Test & Measurements Lab

*Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, NY 13357
Phone: (315) 895-3371
Fax: (315) 895-3670
e-mail: bob.joy@remington.com*