


DataView V3.2
 HRA
 Model Number
 Part Name
 Drawing Number
 Material :
 Vendor
 Hardness Spec.
 Lab Number
 Comment
 Comment
 Comment
 ** Data **

25 97 557 0 HRC 0 2 0 478 133
 LO: 50 LW: 0 HW: 0 HI: 70 LCL: 0 UCL: 0 RCL: 0
 770
 Sear Safety Cam
 PN 15666
 PM
 Rem
 HR15n 88-92
 5 Pice Sample
 From Mayfield
 Per Craig Becker

1 Apr 04 2008	10:53	81.5
2 Apr 04 2008	10:54	81.6
3 Apr 04 2008	10:54	79.5
4 Apr 04 2008	10:54	81.8
5 Apr 04 2008	10:55	80.6
6 Apr 04 2008	10:55	83.4
7 Apr 04 2008	10:55	87.3
8 Apr 04 2008	10:56	87.1
9 Apr 04 2008	10:56	85.9
10 Apr 04 2008	10:56	86.1
11 Apr 04 2008	10:57	83.8
12 Apr 04 2008	10:57	82.6
13 Apr 04 2008	10:58	85.1
14 Apr 04 2008	10:58	86.8
15 Apr 04 2008	10:58	85.7
16 Apr 04 2008	10:59	84.8
17 Apr 04 2008	10:59	84.7
18 Apr 04 2008	11:00	81.3
19 Apr 04 2008	11:00	85
20 Apr 04 2008	11:00	80.7
21 Apr 04 2008	11:01	85.6
22 Apr 04 2008	11:01	85.2
23 Apr 04 2008	11:01	84.2
24 Apr 04 2008	11:02	85.4
25 Apr 04 2008	11:02	82.2

1	2	3	4	5
81.5	83.4	83.8	84.8	85.6
81.6	87.3	82.6	84.7	85.2
79.5	87.1	85.1	81.3	84.2
81.8	85.9	86.8	85	85.4
80.6	86.1	85.7	80.7	82.2



Avg 83.916
 Min 79.5
 Max 87.3
 St Dev 2.24
 Min - 3 St Dev 72.77
 Max + 3 St Dev 94.03