







## Part Breakdown New Parts Trigger Block Trigger Block Screw Modified or Substituted Parts Receiver Insert Side Plate Trigger Safety Arm Safety Detent Spring Safety Pivot Pin Engagement Screw Obsolete Parts Over Travel Screw Connector March 1 (2015) Remington rome Configuration

## Tooling Required

- Receiver Insert
  - New injection molding tool
- Trigger and Trigger Block
  - New MIM tool required for both
- Side Plate
  - New stamping tool
- Safety Arm
  - New stamping tool

March 17, 2015 Skindigton rates Catalyanski