BARBER - RE 0011696

rifle firering without pulling the triger

Discussion Thread

Response (Chris) 10/17/2006 6:51:14 AM Dear Mr. Kostrzewski,

Thank you for your patience. By the serial number your rifle was produced in 1985. We recommend taking/shipping it to a Remington Authorized Repair Center for inspection. If there are worn or damaged parts they can replace them and ensure that it is safe.

I would recommend using our Rem Action Cleaner on the trigger after you receive it back. Use this to clean old oils and debris from the trigger assembly. It is a self-drying product. Re-oil as directed in the owner's manual.

We recommend taking/shipping the firearm to one of the following Remington Premier Repair Centers for inspection.

Send to J & G if you live in the following states: CA, NV, UT, AZ J & G Gunsmithing 625 Vernon St Roseville, CA 95678 916-786-9200 Send to Allison & Carey if you live in the following states: OR, WA, ID, MT, AK Allison & Carey Gun Works, Inc. 17311 SE Stark Portland, OR 97233 Phone: 503-256-5166 Send to Sportsman's Haven if you live in the following states: OH, PA, WV, VA, VT, NH, MD, DE Sportsman's Haven, Inc. 14695 East Pike Rd. Cambridge, OH 43725 Phone: 740-432-7243 Fax: 740-432-3204 Send to Mann & Son if you live in the following states: IL, IN, MS, AR, WI Mann & Son Sporting Goods 515 W Water St. Pinckneyville, IL 62274 Phone: 618-357-2911 Fax: 618-357-3658 Send to Ahlman's if you live in the following states: MN, IA, MO, KS, IN, SD, ND, WY, NE Ahlman's, Inc. 9525 W. 230th Street Morristown, MN 55052 Phone: 507-685-4244 Fax: 507-685-4280 http://www.ahlmans.com/ Send to Sports World if you live in the following states: OK, TX, NM, CO, LA Sports World, Inc. 6841East 41st St. Tulsa, OK 74145 Phone: 918-742-4027 Fax: 918-72-3981

BARBER - RE 0011697

Send to Paducah if you live in the following states: KY, TN, NC, SC, GA, AL, FL
Paducah Shooters Supply, Inc.
3919 Cairo St.
Paducah, KY 42001
Phone: 270-442-3242
Fax: 270-442-5022

Send to Williams Gun Sight if you live in the following states: MI, NY, CT, RI, NJ, MA, ME
Williams Gun Sight & Outfitters
7389 Lapeer Rd., Route #1
P.O. Box 329
Davidson, MI 48423
Phone: 810-653-2131
Fax: 810-658-2140

Include a note of the problem with your name, address and daytime phone number.

You can find additional Remington Warranty Centers for the US and internationally at the following section of our site.

http://www.remington.com/support/repair_services/

To view the warranty for Remington firearms, go to:

http://www.remington.com/support/warranty/

Customer (Michael Kostrzewski) 10/11/2006 8:40:32 PM Dear Sir,

SI#B6695490 Model #700 BDL Caliber 300 Win Mag

I had a problem.

1st time this rifle did this. While hunting Moose in Alberta, My guide aske me to keep shoting after hitting the moose in the sholderand turning it 120 - 160 degrees at 200 yeads. After getinng close I only saw bushes, and antlers. I did what I was requested to do. For 20 yeards I killed lots of bushes. After 3 shots I was empty. The very wounded moose got up and walked 30 yerds and sat down again. My guid say shoot some more. So I reloaded 3 rounds and closed the bolt. The safty was off and the gun fired into the air. Thang God for all the trainaing to ALWAYS POINT A FIRE ARM IN A SAFTE DIRECTIOM! We were both supprised. No finger was on the triger. I held the gun on my thy pointing upward with my left hand on the upper stock and my other hand was closing the bolt.

Just for you to know, that scared the mouse and it stumbled 20 yeard and droped. A GOOD LUNG SHOT and it took a couple of moment to finally suucume. I'd say 2-3 minutes from the 1st shoot. I'd prefer 2-3 seconds, that was me not you firearms.

This particulat rifle has brought home 5 animals, 5 elk. Last year a 6X6. My frieend got a 7X7, pluse his moose this year with a 700 BDL. This is the 1st of the 5 of 6 it did not just drop, so no second shots were required.

However on the forering range I take 3 shots in a row and the safty is off between shots and this has neve happened. And this is over 10 year pluss. All I ever shoot is my hahdload as do the 2 gentalmen I hut with.

I own 3 model 700 and the friens I hunt with each own one (308 & 7mm).

I want to know why this may have happend and what to do to make sure it never happens again.

BARBER - RE 0011697

BARBER - RE 0011698

As the oldest continuous manufacture of fire arms in the US I am asking for support. NOT necessarly an answer. Safty realy matters!

Sincerly

Michael Kostrzewski PhD PE

PS I'll be loking forward to a reply.

No matches were found.