

BARBER - RE 0011746

Model 700 accidentally firing

Discussion Thread

Response (Mark) 5/7/2007 4:25:14 AM

Michael,

Remington has the Safety Modification program. If the gun is returned to our firearms factory, the trigger will be inspected, the bolt lock removed and trigger replaced if necessary. The cost for the program is \$20.00 plus shipping and handling. Details can be found at the following link

http://www.remington.com/safety/safety_center/safety_modification_program/

Customer (Michael Barber) 5/4/2007 5:28:22 PM

I own a Model 700 7mm Rem Mag, twice it has fired when I pushed the safety off. This is a serious safety concern. I have read this has happened before to Model 700 rifles. Please tell me if Remington has a fix for this problem and how I can get my rifle fixed. I am affraid to use it in its current condition.

BARBER - RE 0011746

RE0011686