

FEB. 7, 1990  
2641 MENDOWOOD  
CARMUS CHRISTI, TX.  
78412

REMINGTON ARMS CO. INC.  
ARMS SERVICE DIV.  
ILION, NEW YORK  
13557

DEAR SIR,

MY REMINGTON MODEL 700 .270 CAL RIFLE,  
SERIAL # A6898471, HAS MISFIRED FROM THE SAFETY  
POSITION TO THE FIRE POSITION.

THREE TIMES IT INADVERTANTLY FIRED AS I UNLOADED.  
ONE TIME IT FIRED AFTER I HAD LOADED FOUR CARTRIDGES  
IN THE CLIP, ONE IN THE CHAMBER. I PLACED IT ON SAFE  
THEN AS I MOVED IT FROM SAFE TO FIRE POSITION, THE  
RIFLE FIRED.

I ENCLOSE THE RESULTS OF AN INSPECTION FROM  
CHARLEY'S GUN SHOP. I HAVEN'T FIRED IT SINCE.

I UNDERSTAND THERE WAS A RECALL OF THIS MODEL  
ABOUT 3 YEARS AGO. THIS GUN IS IN THAT RANGE.

PLEASE DO WHAT YOU CAN TO SQUARE THIS PROBLEM  
AWAY. I'LL FEEL A LOT SAFER.

SINCERELY,  
Quincy J. Boyfield

512 937 5262