

BARBER - RE 0011774

Remington 30-06 BDL Model 700

Discussion Thread

Response (Ron) 1/7/2008 5:27:02 AM

Dear Jim,

Thanks for contacting Remington Country. Your gun needs to be sent back in for a Safety Modification. Call us at 1-800-243-9700 for more information.

Customer (Jim Keal) 1/2/2008 5:09:21 PM

My Remington discharged when I was unloading the other day. No injuries or bad consequences, except it scared me terribly. I was doing some reading and I was wondering if there is a fix for this at this time. There are some articles on the internet about this happening to others. I could not get it to do this again while testing it unloaded. My serial is # A6671658.

BARBER - RE 0011774

RE0011714