

Remington



REMINGTON ARMS COMPANY, INC.

TELEX
964-201
STRATFORD, CT

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

939 BARNUM AVENUE
P.O. BOX 1939

TELEPHONE
203-333-1112

BRIDGEPORT, CONNECTICUT 06601

April 28, 1982

VIA EMERY EXPRESS

James D. Huegli, Esq.
Schwabe, Williamson, Wyatt, Moore & Roberts
1200 Standard Plaza
1100 S. W. 6th Avenue
Portland, Oregon 97204

Re: See v.
Remington Arms Company, Inc.
P604-8934, PD186-

Dear Mr. Huegli:

Enclosed are Remington documents produced in compliance
with Plaintiff's Request for Production 1-6.

Very truly yours,

REMINGTON ARMS COMPANY, INC.


R. B. Sperling
Associate Counsel

RBS:hss

3cc: Liberty Mutual
No Enclosures

Enclosures

REQUEST FOR PRODUCTION NO. 6

In February of 1980, Remington had a small recall concerning some 350 Model 700's that were suspected of leaving the factory in January of 1980, having an improperly plated sear safety cam. It was thought possible that the improper plating could wear away and then, under certain conditions, rust could form, and if the build up was sufficient, the rust might render the safety on the gun inoperative. See attached notice letter samples. Recall, for the most part, was confined to contacts with our wholesalers.

Remington.



REMINGTON ARMS COMPANY, INC.

TELEX
964-201
STRATFORD, CT

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS
BRIDGEPORT, CONNECTICUT 06602

TELEPHONE
203-333-1112

February 11, 1980

Gentlemen:

A few Model 700 Center Fire rifles of recent manufacture were shipped from our Ilion, New York factory that were not up to Remington quality standards. We feel these guns may have a safety related problem. They should not be used prior to our inspection.

Through tracing these guns, it was determined that some of the guns in question were sent from Jerry's Sport Center to your location. The specific guns in question are indicated on the attached sheet.

For Guns In Your Inventory

For these guns still remaining in your inventory, please return them, freight collect, to:

Remington Arms Company, Inc.
Attn: D. J. Sanita
Ilion, New York 13357

Mr. Sanita has been alerted to expect your shipment. He will inspect the guns to ensure they meet our high standards and will return them to you within five days after they are received.

For Guns That Have Been Sold

If you have already sold the guns in question, please indicate to whom they were sold so that we can make further contact.

We sincerely regret the inconvenience this has caused you and will naturally reimburse you for the freight expense of returning the guns.

Thank you for your support of Remington products.

Sincerely,

Remington.



REMINGTON ARMS COMPANY, INC.

TELE
964-201
STRATFORD, CT

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS
BRIDGEPORT, CONNECTICUT 06602

TELEPHONE
203-333-1112

February 21, 1980

Dear Mr.

Thank you for your recent purchase of a Remington Model 700 rifle.

Several Model 700 rifles of current manufacture were shipped from our Ilion, New York plant that were not up to Remington quality standards. Through the cooperation of your local Best Products store in Lynchburg, the gun in question (#A6779908) was traced to your purchase.

Your gun is suspected of having a safety related problem. Do not use the gun prior to our inspection. Please return your rifle to:

Remington Arms Company, Inc.
Attn: D. J. Sanita
Ilion, New York 13357

Mr. Sanita has been alerted to expect your gun within the next several weeks. He will ensure your gun meets our high standards and will ship it to you within two days after we receive it.

We sincerely regret the inconvenience this has caused you and will naturally reimburse you for the freight expense of returning the gun.

Thank you for choosing a Model 700 and for your support of Remington products.

Sincerely,

Paul H. Holmberg
Marketing Manager
Firearms

PHH:daf

cc: D. J. Sanita