

P.I. ND GUN EXAMINATION REPORT NUMBER: 234 MODEL: 700 BDL
GENERAL CONDITION: NEW R #: CG930
OUTSIDE WORK: SCOPE USED DATE: 2/23/80
FROM: W.R. FRANTZ
FIRED AMMO TYPE: UNKNOWN ENNIS, TX
& CONDITION: UNKNOWN GUN #: AG785377
PROOF: REP INSP.: 52 TEST: 57 CODE: PJ = 6/79
HEADING: OK GA./CAL.: 30-06
BREECH OPENING: ✓ CHECKED BY: RL/ay
RECOIL SHOULDERS: OK APPROVED: G.M. 3/4/80
CHAMBER: ✓ APPROVED: PLD 2/4/80
TEST: BENCH - OK APPROVED: P.E. 5-4-80
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: WAW 3-4-80
SCOPE HOLE PLUG SCREWS MISSING

COMPLAINT: "UPON MOVING THE SAFETY TO THE OFF POSITION,
THE GUN DISCHARGED -- "

INCIDENT: _____

COMMENTS: Bar lift .0105, Passed Trick test.
Unable to duplicate customer complaint.

Remington-



REMINGTON ARMS COMPANY, INC.

PETERS



SPORTING FIREARMS
TRAPS
POWDER METAL PARTS
RIFLE NEW YORK
AMMUNITION BRIDGEPORT CONNECTICUT
IONORE ARKANSAS

MANUFACTURERS OF
SPORTING FIREARMS. AMMUNITION
TRAPS TARGETS

ILION, NEW YORK 13357

PETERS CARTRIDGE DIVISION
BRIDGEPORT CONNECTICUT
TARGETS ADA OKLAHOMA
ATHENS GEORGIA
PINEBLAY OHIO
CARE HARTLEY BRIDGEPORT

Mr. W. R. Franz
1709 Williamsburg Circle
Ennis, Tx. 75119

August 25, 1980

Model 700 rifle A6785377
Repair Order R-6930-700

Dear Randy,

Thank you for your letter of August 8th, regarding the above subject Model 700 rifle.

In checking our files, we do find that your complaint report does indicate that your customer's name is William Parker, 603 East Sand Stone, Llano, Texas.

If we can be of further assistance in this matter, please let us know.

Cordially,

G. G. Dekanek:cm

Arms Service Division

• SENDER: 1. EACH YELLOW COPY
2. WHITE AND PINK COPIES TO PERSON ADDRESSED

• RECIPIENT: 1. WRITE REPLY AT BOTTOM
2. RETAIN WHITE COPY, RETURN PINK COPY TO SENDER

Remington

PETERS
177

TO

Mr Cole

RUC

SPEED MAIL

REMINGTON ARMS COMPANY, INC.

928 BARNUM AVENUE

BRIDGEPORT, CONN. 06602, U.S.A.

CABLE-HARTLEY, BRIDGEPORT CONN

TELEX: 944701 STRATFORD, CONN

SUBJECT

M 700 BDL

DATE
18 Aug 80

M
E
S
S
A
G
E

I RECEIVED A Model 700 From Elton
S.N. A6785377 THAT EVIDENTLY HAD BEEN
REQUIRED.

PLEASE LET ME KNOW WHAT WAS
DONE AND WHO THE CUSTOMER WAS ON
THE COMPLAINT FORM.

I USED TO DELIVER THIS GUN BUT
DON'T KNOW TO WHOM.

Thanks

SIGNATURE

Randy

NAME

W.R. Francis

POSITION

RECEIVED

R E P L Y

DATE



QCH:AC 8/22/80 24

REMINGTON ARMS COMPANY, INC.

FIREARMS, AMMUNITION, TARGETS, AND TRAPS



BRIDGEPORT, CONN. 06602

E MAIL
TANCE
CHECKED

X ILION, N. Y. 13357

INVOICE NO **R-20661**

INVOICE DATE

SHIP TO

OLD
TO

**FRED'S REPAIR SERVICE
9711 GRANGER H.E.
ROCKFORD, MI 49341**

LR ORDER NO **R-20661-R/742**

OUR ORDER NO.

SHIP: VIA UPS

**N/742 308 #A7221736 OT
w/studs & swivels
L/flip**

RETURNED AS RECEIVED - CUSTOMER'S PROPERTY

TOTAL REPAIR CHARGE

INSURANCE

CANCEL POST

UPS 2.40

TOTAL CHARGES 2.40

CUSTOMER'S SIGNATURE ►

AUG 25 1980

RECEIVING and ESTIMATE REPORT

ORDER R

DATE

RECEIVED 8-6-80 ESTIMATED 8-18-80 VIA CP CHARGES 100

FROM Fret's Repair Service

9711 Grange N.E., Rockford, Mich.

MODEL and GRADE 742 308

GRADE CODE

SERIAL NO A7221736

DATE CODE

IF COMPUTER REFER. ONLY

u/ Start + Solv.
L/Cip

REPAIR CHG.

PARCE POST

TOTAL

IN CONDITION: New (Slightly worn) (Very worn) (Misused) (Quote)

STOMER'S COMPLAINT

gun was in fire

MAIN FAULT

~~Things damaged beyond repair~~

GALLERY REPORT

DEMERIT CODE

~~Fret's Repair Service~~

6-14