

cust. Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 000219
OUTSIDE WORK: No DATE: 1-4-72
FROM: BAY CITY HDQ. CO.
FIRE AMMO TYPE: - BAY CITY, MICH.
& CONDITION: _____ GUN #: 6425267
PROOF: RE.P.-K ^{ASSEMBLER C} INSP.: 74 TEST: 87 CODE: CU = 4/71
HEADING: O.K. GA./CAL.: 300 WIN. MAG.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTS.TRIGGER PULL 5 POUNDS, HORIZONTAL ENGAGEMENT .020
(MIN. IS .020) VERTICAL ENGAGEMENT .035 (MIN. IS .015)TRIGGER DOES NOT RUB ON TRIGGER GUARD.

COMPLAINT: "WHEN SAFETY IS PULLED BACK GUN FIRES WITHOUT
PULLING TRIGGER."

INCIDENT: FOLLOW DOWN.

COMMENTS: CAN FIND NO DEFECT WHICH MIGHT LEAD TO
THE CUSTOMER'S MALFUNCTION. HIS MALFUNCTION
NOT DUPLICATED.