

I contacted my Remington gun dealer after these recent incidents. He informed me that WD-40 would cause the firing mechanism to stick on cold days. I can not imagine that WD-40 would cause this severe a problem. I would like to know what Remington's experience has been with WD-40 and other oils and if the oil could have possibly caused the problem.

Also, I would like to know if there has been a recall of any sort on either gun. I want to know what Remington will do about the problems that I have encountered with these particular Remington models.

Please reply to this letter because I, as my father, have been an avid Remington gun users for many years.

Sincerely,

*Douglas R. Berry*

Douglas R. Berry

DRB:cs

283