CENTER FIRE RIFLES AND PISTOLS - contd.

Caliber 350 Remington Magnum - contd.

Sales suggested a tag be attached to the rifles advising the customer regarding the scope mounting. R & D would normally plan on covering in the instruction folders.

A model gun with the raised Barrel Bracket was shown to the committee. Because the raised section is approximately the same height as the rib, the appearance was considered satisfactory.

Sales requires five (5) model guns to field test ammunition and rifles in October. R & D will assemble the guns with the field test ammunition and rifles in October. R & D will assemble the guns with the field test ammunition and rifles in October.

Committee Action

The committee approved the design change to the Barrel Bracket and suggested the use of an information tag advising the customer of the proper scope mounting.

PIRE RIPLES

2002 P

NYLON 76 LEVER ACTION RIM PIET RIPLES

Sales has disposed of the warehouse quantities of Nylon 76 Leyer Action Rim Fire rifles and stated that additional guns Lever Action can be acid.

> The Ilion Plant has reviewed the status of major components. The quantity of parts to be held for Arms Service sale and gun repair has been rechecked. Planning reaffirms that fourteen hundred (1400) additional guns, assuming normal scrap, can be produced to the warehouse.

83