

Coral Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: GOOD R #: 23155
 OUTSIDE WORK: NO DATE: 11-18-71
 FROM: BIGGS SPT. GDS.
 FIRED AMMO TYPE: - PENSACOLA, FLA.
 & CONDITION: _____ GUN #: 6344022
 PROOF: R.E.P.-A INSP.: J TEST: 87 CODE: KT = 5/70
 HEADING: O.K. GA./CAL.: 22-250
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTS.

TRIGGER CONNECTOR 1.091 (MID=1.093) TRIGGER 1.068 (MID=1.073)

CONNECTOR - SEAR ENGAGEMENT 1.030 MIN. .015, TRIGGER
PULL = 4 TO 4 1/2 LBS. LUBRICANT USED APPEARS TO BE TOO
HEAVY.

COMPLAINT: WHEN PUSHING SAFETY OFF THE GUN GOES OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: WITH THE EXCESSIVE CLEARANCE BETWEEN THE
TRIGGER CONNECTOR AND TRIGGER AND HEAVY LUBRICANT,
THE TRIGGER CONNECTOR PROBABLY WORKED UP UNTIL
IT CAUGHT ON THE SEAR, FAILING TO RETRACT INTO
COCKED POSITION, PUSHING THE SAFETY OFF, THEN WOULD
RELEASE THE FIRING PIN FORWARD TO STRIKE THE PRIMER.