

RECEIVING AND ESTIMATING REPORT

INITIAL FPS		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/07/90	DATE OPENED 12/13/90	DATE CODE RX 11-73	SERIAL NUMBER 6686425	MODEL AND GRADE 700 7MM MAG	BDL	ORDER R 90-325	
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:

BILLS SPORTING GOODS
1016 S. LYNN RIGGS
CLAREMORE OK 74017

SHIP TO:

BILLS SPORTING GOODS
1016 S. LYNN RIGGS
CLAREMORE

OK

74017

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:



NEW



SLIGHTLY WORN



VERY WORN



MISUSED



MARRED

CUSTOMER'S REQUEST

off discharges sometime when safety is taken

MAIN FAULT

*Trigger has been improperly adjusted outside factory - adjust
moving from trigger pull and overtravel adjustment screws. Trigger pull
measured at 1 1/2 pounds pull (no trigger attraction), excessive overtravel.*

PARTS

*Offer to properly re-adjust present
trigger assembly or, we can install
a new trigger assembly at 1/2 normal
cost, as a gesture of good-will.*

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/5