

TABLE 6

MODEL 742-760 "BDL" GRADE

ADDED DIRECT LABOR COSTS FOR IMPROVED METAL FINISHES

	<u>Direct Labor</u>
Barrel	\$.24
Receiver	.11
Trigger Guard	.09
Front Sight Ramp & Rear Sight Base	.01
Magazine Box	.01
	<hr/>
Total Direct Labor	\$.46

Adds to Model 742 Factory Cost	\$ 2.37
Adds to Model 760 Factory Cost	\$ 2.34

Expenditures Required

Capital	\$33,000
Operations	\$11,000
	<hr/>
Total	\$44,000

83