

N/A 100 Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 VARMINT
GENERAL CONDITION: NEW R #: 014704
OUTSIDE WORK: SCORE MOUNTED. DATE: 7-21-72
FROM: BILLINGS P.D.
FIRED AMMO TYPE: - BILLINGS, MONT.
& CONDITION: _____ GUN #: 318117
PROOF: R.E.P. ^{ASSEMBLER #65} INSP.: 79 TEST: 55 CODE: RP = 1/67
HEADING: _____ GA./CAL.: 22-250
BREACH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: _____ APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: "GUN FIRES ON CLOSING THE BOLT," ALSO REPORTED TO
KEYHOLE.

INCIDENT: FOLLOW DOWN

COMMENTS: THE FOLLOW DOWN WAS A RESULT OF THE BROKEN
TRIGGER CONNECTOR FAILING TO RETRACT.