

Bi-Mart

5976 SW 185th

Aloha OR 97007

Dir Sir

The Customer claims that the Rifle  
Started firing when the bolt is locked  
into place when he last purchased it  
Three years ago. If possible please check  
the Rifle and determine if it is a  
Workmanship Defect. Then contact either  
Linda or Todd at (503) 649-6530  
For further instruction.

Thank you  
Jill Walker