

BARBER - Kinzer PPS GAL RE0000560

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R # : 002116
 OUTSIDE WORK: SCOPE MOUNTED - REAR SIGHT DATE: 2-1-72
REMOVED FROM: BLISH, MIZE & SILLMAN, INC.
ATCHISON, KANSAS
 FIRED AMMO TYPE: - GUN # : 6362366
 & CONDITION: _____ CODE: WT = 8/10
 PROOF: R.F.R.-E INSP.: 73 TEST: 13 Gx./CAL.: 270 WIN.
 HEADING: _____ CHECKED BY: C. PROSSER
 BREECH OPENING: O.K. APPROVED: _____
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO BROKEN, ETC. COMPONENTS. SIDE BURR ON TRIGGER
& CONNECTOR. TRIGGER FULL STROK. ENGAGEMENT .007 (MIN.
IS .020) NONE OF SCREWS SEALED. ENGAGEMENT
SCREW STAKED BUT NOT HOLDING. LOADED CARTRIDGE
ON CONNECTOR NOT HORIZONTAL.
 COMPLAINT: RIFLE FIRED PREMATURELY,

 INCIDENT: FOLLOW DOWN

 COMMENTS: THE COMBINATION OF INSUFFICIENT ENGAGEMENT &
BURRS PROBABLY PREVENTED THE CONNECTOR-TRIGGER
FROM RETRACTING INTO FIRING POSITION CAUSING THE
FIRING PIN TO FOLLOW DOWN.