MINUTE #15 - 1971

(

(

1

n National States

ſ,

23

83 S

WIL02149

SHOTGUNS

MODEL 1100, 20 GAUGE LIGHTWEIGHT SHOTGUN

Production reported on the Bridgeport endurance testing of three Model 1100, 20 gauge lightweight shotguns as follows:

<u>Gun No.</u>	Rounds	Failure Since Last Report
1	7030	Operating Handle Retainer Plunger Restake Shell Latch
2	9795	No testing .
3	9435	Interceptor Latch Extractor broken Feed Latch-finger piece broken Fore-end - tabs broken

MODEL 1100, 12-20 GAUGE LEFT HAND SHOTGUNS (Introduction 1972)

Production reported that Model 1100, 12 gauge left hand shotguns are scheduled to be manufactured in December.

Trial and pilot operations on 12 gauge magnum left hand gun components are in progress and will be completed in October. Production is scheduled for January, 1972.

The stem chamber - left malfunction on the Model 1100, 20 gauge Left hand shotgan has been corrected by changing the Carrier. The gun has been released to production which is scheduled for December.

MODEL 870, 20 GAUGE LIGHTWEIGHT SHOTGUN (Introduction 1972)

5

Production reported that General Management did not approve the production sample Model 870, 20 gauge lightweight shotgun presented in July. The action did not operate smoothly. Revisions have been made to correct this condition and a new sample will be presented, probably before the October meeting.

]