

(E)XACT 10/02/9
08 59 51
MODEL: 700
BA/CAL: 30-06
TYPE: BDL
ACCESSORIES: W/STUDS

This is most disconcerting and dangerous.
It does not, however, do this
every time.

IS: WU 8-71
HER ACCESSORIES:
REAR SIGHT

2. After firing a round and
another is bolted, the weapon
may or may not fire as
soon as the bolt is fully
closed - very dangerous

ENTERED BY: LCS
REPAIRMAN:
TYPIST:
CORRESPONDENT:
PFS = PRINT R&E

Please correct (repair)
nos. 1 & 2 above. If a
retrofit is available to allow
ejecting a round while still
on safe, please do so.

CAROL M.

I don't need an estimate - just
let me know how much

Rodney M. Bourgeois

6 La Combe Harbor Lane, P.O. Box
La Combe, La 70445 907

many thanks
Rodney M. Bourgeois

