

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-09811

CUSTOMER ORDER NO.

W/BUSHNELL SPORTVIEW 4X32 SCOPE

J.M.

E RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

4/12/93

04/14/93

LW 2-72

6526682

700 270

ACCESSORIES

L/WOOD

SCOPE MNTS

SCOPE BASE

M:

BRAINARD, ROGER
MCGREGOR GUNSMITH
910 W MAIN RR
MCGREGOR

IA 52172

SHIP TO:

BRAINARD, ROGER
MCGREGOR GUNSMITH
910 W MAIN RR
MCGREGOR

IA
52172

CUST NO: 077992 C.D.D.L.

QUANTITY

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

4/22/93

UPS

CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

DAMAGED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

LE

A1

B1

RIGGER GROUP

B2

E1

F1

T ASSY.

B3

E2

F2

REL ASSY.

B4

D1

F3

ASSY.

B5

D2

E4

F4

D

C1

D3

E5

F5

AL

C2

FAULT

Unable to cycle in check complaint. Rifle moved with all
action components disassembled. Trigger assembly also removed from
receiver assembly. Trigger adjustment screws tightened with outside pliers.
Trigger contact has been removed.

COMMENTS

Revised complete trigger assembly
at 1/2 manual adjustment test.
Then action, as previously compressed
of ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE