


EXHIBIT 6C

B



MISSING: ONE  
CARRIER LATCH  
PIVOT PIN

W




EXHIBIT 6C