

BOLD 3152

Dear Sir

I Am RETURNING my 700 BDL
2506 RIFLE BECAUSE THE
TRIGGER IS NOT WORKING AS
IT SHOULD IT HAS FIRED
when you push the safety
OFF IT HAS done this
more than once. I had
A gunsmith check it and
TALKED TO your service people
they said to RETURN IT.

RICHARD BRENNEMAN
RD 3 BOX 356V
Huntingdon, PA.

16652

Phone 814-643-5296

JG REPORT

15-06 BDL ORDER
R 90-333

SHIP TO:

BRENNEMAN, RICHARD
RD 3
BOX 356V
HUNTINGDON

PA
16652

PROM. DATE ESTIMATED VIA
UPS

PARCEL POST TOTAL

WORN ☐ MISUSED ☐ MARRED

it should it has fired

trigger assembly has been
sent minus from all
me. at 24-2 1/2 months, 2)
not fully satisfied on working

the trigger will not even move off trigger

Send again sent for new trigger assembly
at 1 month cost, as gesture of good
will.

Rifle is 15 years old

REPAIRMAN 7/1	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY