

MODEL 3200MODIFICATION COST ESTIMATESUNIT FULL BOOK COST

OCTOBER, 1974	ESTIMATE	\$ 60
MARCH, 1975	ESTIMATE	\$130

THIS COST IS DUE TO THE LABOR, MATERIAL AND EXPENSE INVOLVED  
IN MAKING AND INSTALLING ADDITIONAL COMPONENTS AS FOLLOWS:

	<u>ESTIMATED REPLACEMENT PERCENTAGE</u>	
	<u>OCTOBER, 1974</u>	<u>MARCH, 1975</u>

BOTTOM TANG	30	100
JOINT PINS	0	100
STOCK	0	60
FORE-END	0	40
FRAME	0	12
TOP LOCK	0	5

AVERAGE NUMBER

SMALL PARTS	10	24
-------------	----	----

	<u>ESTIMATED ADDITIONAL</u>	
	<u>REWORK PERCENTAGE</u>	

REFIT STOCKS	0	40
--------------	---	----

JHS:I  
3/14/75

EXHIBIT 19