

REMINGTON ARMS COMPANY, INC.  
INTER-DEPARTMENTAL CORRESPONDENCE

*Remington*  


cc: Area Managers  
Regional Managers  
R. A. Partnoy  
J. E. Dickey  
J. G. Williams

Bridgeport, Connecticut  
December 12, 1972

**U R G E N T !**

TO: ALL FIELD REPRESENTATIVES

FROM: E. G. LARSON

RE: REMINGTON AND PETERS SP16RS AND PS16RS SLUG LOADS

Air Mail letter

The attached ~~night-vision~~ <sup>83</sup> was sent to distributors to whom we shipped the above slug loads during the period from September 1, 1971 to December 1, 1972.

As noted in the letter, we have found undersize slugs that may produce less-than-normal ballistics, including the possibility of leaving a slug in the barrel on firing.

The codes involved (found on surface of inner box flap) are:

-U--L--  
-U--B--  
-W--K--  
-W--S--  
EXAMPLES: BU01L20  
AU17L20

THE IMPORTANT PART OF THE CODES ARE THE CAPITAL LETTERS:

U--L  
U--B  
W--K  
W--S

IF THESE SHOW ANYWHERE IN THE CODE, RETURN THE AMMUNITION

We have pulled all invoices relating to above. Attached are copies of these invoices pertaining to your specific wholesalers.

Immediately on receipt of this letter, we ask that you contact each of the wholesalers noted, advise them of the problem, and ask their cooperation in having the ammunition returned.

*Enclosure 1*