

LIMITED DISTRIBUTION

PRODUCT SAFETY SUBCOMMITTEE MEETING
OCTOBER 23, 1978

MINUTE #1 - 1978

PRESENT:

<u>SUBCOMMITTEE</u>	<u>OTHER</u>
E. F. BARRETT, CHAIRMAN	J. H. CHISNALL
R. A. PARTNOY	J. E. PREISER
E. G. LARSON	A. W. BELL
E. HOOTON	H. D. ALBAUGH
	E. S. McCAWLEY
	R. B. SPERLING, ACTING SECRETARY

MOHAWK MODEL 600, ETC.

REDACTED
PRIVILEGED

Status of the John Coates case and strategy in light of same.
ATTORNEY CLIENT—WORK PRODUCT

Since the guns can be fixed by the substitution of a new trigger assembly, the Subcommittee determined that the most expeditious method to affect this correction would be to refer gun owners to the nearest Remington recommended gunsmith in their area.

REDACTED