

LIMITED DISTRIBUTION

PRODUCT SAFETY SUBCOMMITTEE MEETING
OCTOBER 30, 1978

PRESENT:

SUBCOMMITTEE

E. F. BARRETT, CHAIRMAN
R. A. PARTNOY
E. G. LARSON

OTHER

J. E. PREISER
H. K. BOYLE
R. B. SPERLING, ACTING SECRETARY

MOHAWK MODEL 600, ETC.

It was reported that every replacement trigger assembly is being gauged at Ilion and a 10% quality check is being conducted.

Remington Representatives are now in Texas to review recommended gunsmiths' procedures on correcting guns and to see what, if any, problems are being encountered.

R. B. Sperling
Acting Secretary

RBS:hss

WIL06640