

were damaged with 7mm Express Remington ammunition. Remington is going to perform a hardness test on the accident cartridge to determine if a soft head could have contributed to the high pressure accident.

Another meeting is scheduled for June 26.

R. A. Partnoy
R. A. Partnoy
Acting Secretary

83

CONFIDENTIAL