

of mixed powder and thin webs in the ammunition in question; but even so there would be no gun damage and no safety hazard when such ammunition is fired in a Model 700.

The Chairman noted that although these results are supported by the investigations to date, similar tests should be conducted with a Remington Model 742 rifle, which represents the minimum chamber strength condition for a rifle of the caliber in question. Ammunition Research said they would conduct such tests.

*B. K. Daubenspeck*  
B. K. Daubenspeck  
Secretary

CONFIDENTIAL