

TABLE 1

44 EXPRESS REMINGTON
HIGH PRESSURE HANDLOADS FIRED IN REMINGTON R742*

<u>4198 Powder Charge Wt. (grains)</u>	<u>Average Pressure (psi)</u>	<u>Remarks</u>
45	71280	Five rounds fired. Shells extracted manually by operating bolt handle or with light tapping. Headspace did not increase.
46	76380	Three fired cases could be removed by operating bolt handle or by light tapping. Two cases stuck and had to be pried out. Headspace increased. Bolt closed on No-Go, did not close on field gauge.
47	82020	Five rounds fired. Cases removed by tapping bolt handle. Bolt closed on No-Go, did not close on field gauge.
47.7	85820	Four rounds fired. Two cases removed by tapping bolt handle. Two stuck in chamber and had to be pried out. Bolt closed on No-Go, did not close on field gauge.
48.3	90420	Two rounds fired. Both cases stuck in chamber and had to be pried out. Bolt closed on field gauge after first shot.
48.8	94380	Two rounds fired. First case stuck and had to be pried out. Second shot blew gun.

Note: No-Go gauge headspace of 2.1070"; field gauge headspace 2.1082".

*Serial Number SNB7336291

ADMCD - 2/80