

GUN DAMAGE									
6MM 80 GR. HPPL - 7514 L. MOER									
FILE #	NAME	RECEIVED LOCATION DATE	CODE	AMMO CONDITION	GUN CONDITION	PERSONAL INJURY	RETURNED AMMO PRESS.		
							R	IND	
R15872 90468F	G. Center Buffalo, NY	(I) 6/15/82	S25I	Severe Head Expansion	788-Bolt Shroud Damaged Bolt Replaced	No	536	557	
R11091	G. Isam	(I) 11/4/82	S30I		700 Var.-Extractor Replaced	No	537	583	
R06510 90468A	Red Owl Family Pierre, SD	(I) 2/3/83	S25I	Severe Head Expansion	788-Bolt Shroud Damaged Returned Unrepaired	No	555	614	
R11720	George's Gun Shop Peterson, IA	(L) 4/11/83	S30I	Blown Primers	760-Dust Cover Blown Off	No	516	559	
R14489 90468D	Dick's Sptg. Binghamton, NY	(I) 5/26/83	S25I	Minor Head Expansion	788-Bolt Locked Up Repaired M/C	No	548	610	
R12154	David Brewer Speedwell, VA	(I) 6/21/83	S02N	Severe Head Expansion	700-Bolt Damaged Repair in Process	Minor	573	586	
R15942 90468H	Jorgensen's Spts. Williston, ND	(I) 6/23/83	S30I	Severe Head Expansion	788-Bolt Shroud Damaged Replaced Bolt	No	518	531	
R12150	Halan Jerabek Hutchinson, MN	(I) 6/24/83 3/11/75	S25I C11F	Head Separation	700-Bolt Shroud Damaged Replaced Bolt	No	539 577	573 600	
R16874 90468E	Shawmut Dist. Kittery, ME	(I) 7/12/83	S25I	Case Separation	742-Locking Lugs Damaged Replaced Gun	No	586	670	
R16835 90468G	Mountaineer Spts. Martinsburg, WV	(I) 7/13/83	S25I	Severe Head Expansion	700-Bolt Shroud Damaged Replaced Bolt	No	576	724	
R12121	Steve Yancey Van Vuzen, MO	(L) 6/20/83	S25I	Blown Primers	700-Broken Extractor	No	555	625	
R18026 90468C	Dick's Sptg. Binghamton, NY	(I) 8/83	S25I	Head Expansion	788-Bolt Locked Replaced Bolt	No	538	566	

SAAMI
MAX. PROD. AVERAGE 552
MAX. IND. 639
NOMINAL 520
MIN. PROOF 640