

RECEIVING AND ESTIMATING REPORT

DATE		DATE CODE		COMMENTS		ORDER	
07-31		07/07		JIM STEKL "B"		R 72-1462	
ACCESSORIES		SERIAL NUMBER		MODEL AND GRADE			
		11-001081		7000		B01	

FROM:

SHIP TO

ACCOUNT NUMBER

063163

REPAIR CHARGE

40.00

TAX ST

TAX LTY

NET PRICE

01-007972-3
01A 7331235

ESTIMATE

ESTIMATE

6.2388

4.09

\$ 440

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☒ VERY WORN☐ MISUSED☐ QUOTE

CUSTOMER'S COMPLAINT

"Gun fired when pressure built, then it was full"

MAIN FAULT

Stock Marvel -

Tugger was the same as the one reported out of factory -
Tugger pull 6 1/2", was very tight, not enough resistance
insufficient resistance adjustment could be made to
to maintain old one as before

PARTS

3435 Tugger easy BCC could not be adjusted Tugger easy
Tugger easy BCC could not be adjusted Tugger easy

P. 6435

polished Chamber
Check Headings

FOR COMPUTER REF ONLY

ESTIMATE

DEPARTMENT

ML