

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 000999
OUTSIDE WORK: NO DATE: 1-12-72
FIRE AMMO TYPE: _____ FROM: CADDIE LABAR'S
DISTR. CO.
DALLAS, PENN.
& CONDITION: _____ GUN #: 232943
PROOF: R.E.P. INSP.: ? TEST: 79 CODE: WN = 8/66
HEADING: O.K. GA./CAL.: 280 REM.
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED OR BROKEN COMPONENTS. TRIGGER PULL FOUR
POUNDS, ENGAGEMENT .015, TRIGGER BINDING ON GUARD
SLIGHTLY. GREASE-DIRT COATING ON HIDDEN PARTS
INCLUDING INSIDE & OUTSIDE OF TRIGGER ASSEMBLY.
COMPLAINT: SOMETIMES IT WILL FIRE, OTHER TIMES IT WON'T, SOMETIMES
IT WILL BE A DELAYED FIRING.
INCIDENT: SEAR DOES NOT RELEASE FIRING PIN.
COMMENTS: THE CUSTOMER'S MALFUNCTION WAS DUPLICATED WITH
STOCK IN PLACE BUT WORKED O.K. WITH STOCK OFF.
APPARENTLY THE TRIGGER-TRIGGER GUARD BIND
COMBINED WITH THE TOO HEAVY LUBRICATION WAS
THE CAUSE OF HIS TROUBLE.