

May 9, 1994

Stephen Camp
RR #2 Site 5 Box 27
Winterburn, AB T0E 2N0
Fax (403) 955-8676

Remington Arms

To Whom It May Concern:

I purchased this rifle around 1980; since that time the following problems have ensued:

I have only fired factory loads through this firearm. I save my brass in case I ever wanted to re-load. A friend of mine has a similar rifle and does re-loads. I gave him my brass and he found that the brass was cracked at the neck, in several of the brass.

Also, the rifle did fire upon closing the bolt. At the time I was unsure that the rifle had fired on its own.

Please review these problems and fix, if there is no cost. If there is a cost please fax me for approval prior to proceeding.

If the barrel has to be changed, could you make it a 7mm Mag?

Yours truly,



Stephen Camp

SDC/ems