

RECEIVING AND ESTIMATING REPORT

CUST NO: 051966 C.O.D.		COMMENTS		STEEL	
INITIAL JHM	CUSTOMER ORDER NO.				
DATE RECEIVED 10/25/91	DATE OPENED 10/30/91	DATE CODE DZ 9-75	SERIAL NUMBER A6206590	MODEL AND GRADE 700 270	ORDER R 91-21859
ACCESSORIES		W/STUDS HARD CASE			

FROM: CARIS, NICK
P O BOX 2163
BUCKHANNON
USA WV 26201

SHIP TO: CARIS, NICK
P O BOX 2163
BUCKHANNON
USA WV 26201

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 11/5/91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	----------------------	------------

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

TOMER'S REQUEST

"When putting a shell in the chamber, the gun fires"

FAULT: Cannot duplicate complaint - firing pin could not be made to fall
high enough bolt. However, it was noted that trigger assembly
had been adjusted out of factory - trigger pull below our minimum
requirement (to be 2 3/4 pounds) trigger activation was not consistent
because of light pull - rear lift .007"

We can re-adjust trigger assembly
to heavier pull weight, 2 1/2, offer to
install new trigger assembly at
1/2 normal cost, as a gesture of good-
will, if this will better restore
confidence in the rifle

REPAIRMAN JHM	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90