

RECEIVING AND ESTIMATING REPORT			COMMENTS			ORDER R91-23431		
INITIAL JJM			CUSTOMER ORDER NO.			BOTTOM HALF OF SEE THRU MTS ONLY		
DATE RECEIVED 11/12/91	DATE OPENED 11/18/91	DATE CODE 00 7-77	SERIAL NUMBER A6480720	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	ADL - STEKO		
ACCESSORIES W/STUDS								
FROM:			SHIP TO:					
CARNEYS SHOOTERS SUPPLY ROUTE 1 BROWNING RD MASSENA NY 13662 USA			CARNEYS SHOOTERS SUPPLY ROUTE 1 BROWNING RD MASSENA NY 13662 USA					
ACCOUNT NUMBER			ACCOUNT NUMBER N/C			CUST NO: 008354 C.O.D.		
GUN CONDITION			WRITE ☐ CLEAN/TEST			PROM. DATE ESTIMATED VIA		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE						11/21/91 UPS		
						REPAIR CHARGE		
						EXCISE		
						TAX		
						INSURANCE		
						UPS		
						PARCEL POST		
						TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Cannot duplicate complaint. Rifle operates properly, however, disassembly of rifle revealed the trigger assembly has been adjusted outside factory standard missing from adjusting screws - 1) trigger pull increased over our max spec (at 6 1/2") 2) insufficient over-travel*

See lift - 20 11"

ARTS	COMMENTS					
	<i>Offer to re-adjust and re-real present trigger assembly, or, if owner desires, we can install a new trigger assembly at 75% normal cost, as a gesture of good-will if it will help restore confidence in the rifle.</i>					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	<i>NR</i>					
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91