

BARBER - Kinzer PPS GAL RE0000906

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 91-26680

CUSTOMER ORDER NO.

ATTN: J STEKL

BOTTOM HALF SEE THRU HTS ONLY

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/91	12/19/91	A0 3-77	A6431155		700 308 BDL
SERIES	W/STUDS				

1:

SHIP TO:

CARPENTAR, DON
228 FRONT ST
BRAVAR DAM
USA

WI 53916

CARPENTAR, DON
228 FRONT ST
BRAVAR DAM
USA

WI
53916

CUST NO: 054083 C.O.D

JNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA
				UPS
CONDITION		REPAIR CHARGE		
EW		EXCISE		
SHTLY WORN		TAX		
ORN		INSURANCE		
ERY WORN		UPS		
IREPAIRABLE		PARCEL POST		
		TOTAL		

COMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	B1				
ER GROUP	"When putting the safety off the gun went off and also when putting the safety on E2 it. gun went off"					
ASSY.	B2					
EL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
			C1	D3	E5	F5
			C2			

AULT *No fault found. Cannot duplicate above complaints.
inspect and safety assembly operation properly.
spring pull 4 pounds; rear lift .007"*

COMMENTS		<i>Offer to return rifle as-is as we can install a new trigger assembly with a non-fault code safety at 1 normal cost as a gesture of good-will if it will better restore confidence in the rifle.</i>					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		

RD6925 REV. 8/91