

RECEIVING AND ESTIMATING REPORT						COMMENTS		ORDER R 94-91838	
DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER		NEW SERIAL NUMBER	
01/13/94		01/14/94		LD 2-77		A6424168		500 243	
ACCESSORIES		W/STUDS		SCOPE BASE				MOHAWK	
FROM: <i>K. Suppy</i>						SHIP TO:			
CARROLLS GUN SHOP 1612 N ALABAMA RD WHARTON TX 77488						CARROLLS GUN SHOP 1612 N ALABAMA RD WHARTON TX 77488			
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		CUST NO: 006416 WFLM		PROM. DATE		ESTIMATED	
				WRITE ☐				VIA UPS	
GUN CONDITION						REPAIR CHARGE			
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						20.00			
Product Service						EXCISE			
						TAX			
						INSURANCE			
						UPS			
						PARCEL POST			
TOTAL									
CUSTOMER CONCERN		AMMO		FUNCTION		FINISH		ACCURACY	
CYCLE		B1							
TRIGGER GROUP		B2							
BOLT ASSY.		B3							
BARREL ASSY.		B4							
REC. ASSY.		B5							
WOOD		C1		D2		E3		F4	
METAL		C2		D3		E4		F5	
MAIN FAULT									
<i>Upon receipt, could not duplicate Customer Concern. However, examination of action and trigger assembly reveals that the rifle has been poorly maintained. The action is dirty, the trigger assembly appears to be jammed.</i>									
PARTS					COMMENTS				
<i>Substance Bolt stop where would not lock. Trigger housing moved at user's.</i>					<i>When action & trigger completely trigger assembly at 1/2 normal replacement cost, as per letter of good will.</i>				
REPAIRMAN		PROOF		CLEAN		TEST		PATTERN	
CC									
GALLERY TESTER		DATE		DATE		DATE		DATE	

OFFICE COPY

RD6925 REV. 1/92